

	Stationary Tables	5-Sided Stationary Tables	Mobile Tables	Cobot Tables	Quick-Change Tables
Primary Use	General Manual or Cobot Welding	Large-Scale or Complex Cobot Integration	Mobile Welding or Changing Work Zones	Dedicated Cobot Automation	High-Mix, Low-Volume Cobot Welding
Size Options	36" x 36" 72" x 36"	48" x 48" 96" x 48"	48" x 48" 96" x 48"	36" x 36" 72" x 36"	36" x 36" 72" x 36"
Table Material	Nitride+ or Plain Steel	Nitride+ or Plain Steel	Nitride+ or Plain Steel	Nitride Steel	Steel
Top Thickness	1/2"	1/2"	1/2"	1/2"	1/2"
Flatness Tolerance	+/- 0.015"	+/- 0.015"	+/- 0.015"	+/- 0.015"	+/- 0.01"
Modularity	16mm holes 2" grid	16mm holes 2" grid	16mm holes 2" grid	16mm holes 2" grid	Quick-Change Fixture Plates
Mobility	No	No	Yes	No	No
Load Capacity	1,000 lbs+	6,000 lbs	4,000 lbs	2,000 lbs	2,000 lbs
Adjustability/Leveling	Adjustable Height	Adjustable Height	Fixed Legs with Casters	Fixed Legs	Leveling Feet
Integrated Metal Pegboard	Yes	Yes	Yes	Yes	Yes
Quick-Change Compatible	No	No	No	No	Yes
Cobot Docking Station Compatible	Yes Cobot Pedestal	Yes Cobot Pedestal	Yes Cobot Pedestal	Yes Cobot Docking Station	Yes Cobot Docking Station
Workflow/Automation	Basic Manual Workflow	Complex Manual + Automation Ready	Flexible Workflow with Mobility	Cobot Optimized	High-Mix, Quick-Change Automation
Best For	Manual Weld Shops, Simple Cobot Tasks	Larger Parts, Scalable Coot Systems	Shops Needing Table Mobility	Cobot Prototyping & Production	Fast Setup Changes, Short-Run Cobot Welding

From Manual to Mobile to Cobot-Ready - Flextur Has the Right Welding Table for Every Workflow.